

## Press tool design and analysis for seat frame components

<sup>1</sup>Madhukumar M U, <sup>2</sup>Rthwick P, <sup>3</sup>Puttaswamaiah s & <sup>4</sup>Maruthi B H

<sup>1</sup>Madhukumar M U, M-tech (Machine design), EWIT

<sup>2</sup>Rthwick P, M-tech (Machine design), EWIT

<sup>3</sup>Puttaswamaiah S, Associate Professor, Dept. of Mechanical Engineering, EWIT.

<sup>4</sup>Maruthi B H. Head of mechanical dept. EWIT, Bangalore, Karnataka, India

\*\*\*

**Abstract** - Press tool is an apparatus by which one can cut the material, shape the material, material can be compressed, material can be deformed to the required shape. Press tool is a tool for cutting, forming, drawing or assembling comprising of at least punch and die used in manual or in a power press. The design is done by the Solid Works software. Three important stages are made to complete the design: in these preceding stages the design is optimized from the basic level to working level. The final design of parts is analyzed with the Ansys software. After analysis the results are compared with theoretical results and material properties for validation. After comparing the Ansys results, theoretical results found that the design is safe for further operations. Finally the cost estimation of the press tool calculated.

**Key Words:** Press tool, Ansys, Die, Punch, Seat frame

### 1.INTRODUCTION

#### 1.1 Multiple component press tool

Multiple component press tool is the tool for more than one component accommodate in a single press tool but the pressing work will perform at different instants for the different components. The basic need of this press tool is offsetting tube by its radius to produce the flat surface. This type of operations is rarely performed by the press tool because of the cylindrical surface. This cylindrical surface to position in the die will requires the more precision surface, that surface is requires more precision machining. But in the current process in the single tube component there are more than one positions are there to offset. This process to

perform in the special purpose machine requires more time and the precision of the component is very low compared to the press tool process. In special purpose machine requires well trained operator is necessary to finish this product, but in press tool inexperienced operator can also perform very well. This is because in press tool operation the operator work is only to positioning of the component and after a stroke removing of the component from the press tool.

This press tool consists of the different parts. The different parts of press tool and their uses will be explained bellow.

**Top plate:** This is the major part of the top half of press tool it holds the entire top half parts. It will be further connect to the top ram of the pressing machine by slotted blots and T-grooves.

**Punch back plate:** Punch parts are normally hardened parts. And punches are in the top half of the press tool. In order to prevent the hardened punches to penetrate into top plate we use punch back plate.

**Punch holder:** This is also a plate which holds rigidly the punches in operation condition. In the punch holder pockets are there in that the punch will fit by the fasteners tighten the punch

**Punches:** To perform any cutting or non cutting operation punches will be used.

**Die plate:** In order to locate the part for the operation the die plate will have similar profile of the final product. This plate will help to location and orientation of the part to

produce the final product. It will also help to clamp the part while the pressing operation.

**Die back plate:** Normally die will be hardened. In order to prevent the die to penetrate into the bottom plate the bottom die back plate will be used.

**Guide pillar and guide bush:** The top and bottom half are separated for every strike and they will combine in the press condition. Therefore in order to guide the top in to the bottom half in exact position guide pillars and guide bushes will be used.

**Bottom plate:** Bottom plate is used to hold all the parts of the bottom half together. By this part the bottom half will be connected to the bottom ram by slotted bolts and T-groove arrangement.

**Stripper plate:** After punching the punch should be strip off from the component in order to strip off the punch use the stripper plate.

**Strip guides:** In some cases the stripper is required to guide into the bottom die for clamping purpose use stripper guides.

### 1.1 Components and Their Arrangement

This press tool is use to produce flat surface on the automobile seat frame in the middle sections. This press tool consists of three different components of seat frame. Therefore the arrangement of the components is very important for the further design work. Primarily there are two different component arrangements are done they are called matrices. The two different matrices will be shown bellow. From these matrices the better matrix is selected for press tool design. The selected matrix is such that it is easy to operate in press tool and minimum die size condition. The component arrangement is shown in the bellow figures.




Figure 1: Matrix-1




Figure 2: Matrix-2

For design the matrix-2 is selected and the whole design work will on the basis of the matrix-2 arrangement.

### 1.2 Components Tonnage Calculation

For the components for each section calculated pressing force separately. For the three components the pressing force is same in similar section The similar section deformation force calculation is given

Component press tonnage calculations

$$V_{dr} = f_1 T (2 \pi R C_1 + 0.25 L)$$

$f_1$  = ultimate tensile strength (N/mm<sup>2</sup>)

T = Thickness of blank (mm)

R = Corner radius between the sides (mm)

L = length of box (mm)

C1=constant depending on ration h/R

h= deep of the drawing

R= corner radios

**Component 1 and 2 calculations**

f1=290MPa, T=1.6mm, R=2mm, H=10.40, L=79mm

$$V_{dr}=f1 T (2 \Pi R C1 + 0.25 L)$$

$$V_{dr}=290 \times 1.6 (2 \times \Pi \times 2 \times 2 + 0.25 \times 79)$$

$$V_{dr}=20825=20 \text{ Ton for one side}$$

$$\text{Total force required}= 2 \times 21 = 40 \text{ Ton}$$

**Component 3 calculations**

**Section-1**

f1=290MPa, T=1.6mm, R=2mm, H=10.40, L=120mm

$$V_{dr}=f1 T (2 \Pi R C1 + 0.25 L)$$

$$V_{dr}=290 \times 1.6 (2 \times \Pi \times 2 \times 2 + 0.25 \times 120)$$

$$V_{dr}=25581=25.5 \text{ Ton}$$

**Section-2**

f1=290MPa, T=1.6mm, R=2mm, H=10.40, L=79mm

$$V_{dr}=f1 T (2 \Pi R C1 + 0.25 L)$$

$$V_{dr}=290 \times 1.6 (2 \times \Pi \times 2 \times 2 + 0.25 \times 79)$$

$$V_{dr}=20825=21 \text{ Ton for one side}$$

$$\text{Total force required}= (2 \times 21) + 25.5 = 67.5 \text{ Ton}$$

**2. PRESS TOOL DESIGN**

The press tool design work will be done with the help of the Solid works software. The design will be done by fixing the component on the base plate. At the plane of tube offsetting the tool is differentiated into the top half and

bottom half. Bottom half comprises of the die, spaces, bushes, hooks. Bottom clamp holders and clamping jaws. The top half comprising of the stripper plate, punches, spacers, punch back plate, top plate, pillars and pillar clamping. The design of bottom and top half is shown in the bellow figures.




Figure 3: Bottom half




Figure 4: Top half




Figure 5: Press tool

## 1.2 Theoretical Calculations of the Press Tool parts

### Buckling calculations

#### For pillars

Material= 20MnCr5

Young's modulus E =200GPa

Poisson's ratio=3.0

Yield strength=550MPa

Diameter= 50mm

Length= 290mm

Maximum or critical force  $F = \frac{\pi^2 EI}{(KL)^2}$

Where,

F- Maximum or critical force

E-Modulus of Elasticity

I-Area moment of inertia

L- Unsupported length of column

K-Column effective length factor=2

$F = \frac{\pi^2 \times 200 \times 10^6 \times \pi \times (0.054)^4}{4 \times (2 \times 0.290)^2}$

F=28803.4 KN

$\sigma = \frac{F}{A} = \frac{\pi^2 E}{(l/r)^2}$

But currently force on each pillar is 20 Ton=196.133KN

Therefore  $\sigma = \frac{196.133}{(\pi \times 0.052/4)}$

$\sigma = 99.821$  MPa

In impact load condition  $\sigma_{max} = 2 \times \sigma$

$\sigma_{max} = 2 \times 99.821$

$\sigma_{max} = 199.642$  MPa

#### For guide bushes

Material= 20MnCr5

Young's modulus E =200GPa

Poisson's ratio=3.0

Yield strength=550MPa

Diameter= 50mm

Length= 290mm

Maximum or critical force  $F = \frac{\pi^2 EI}{(KL)^2}$

Maximum or critical force  $F = \frac{\pi^2 EI}{(KL)^2}$

$F = \frac{\pi^2 \times 200 \times 10^6 \times \pi \times ((\pi \times 0.084/4)^4 - (\pi \times 0.06324/4)^4)}{(2 \times 0.140)^2}$

F=494479.8511KN

$\sigma = \frac{F}{A} = \frac{\pi^2 E}{(l/r)^2}$

But currently force on each pillar is 20 Ton=196.133KN

$A = (\pi \times 0.082/4)^2 - (\pi \times 0.06322/4)^2$

A=1.89X10<sup>-3</sup>m<sup>2</sup>

$\sigma = \frac{196.133}{1.89 \times 10^{-3}}$

$\sigma = 103.802$  MPa

In impact load condition  $\sigma_{max} = 2 \times \sigma$

$\sigma_{max} = 2 \times 103.802$

$\sigma_{max} = 207.604$  MPa

#### Stripper tubes

Material= EN-8

Young's modulus E =215GPa

Poisson's ratio=3.0

Yield strength=550MPa

Internal Diameter= 17mm

Outer Diameter= 23mm

Length= 110mm

Maximum or critical force  $F = \frac{\pi^2 EI}{(KL)^2}$

$$F = \frac{\pi^2 \times 215 \times 10^6 \times ((\pi \times 0.0234/4)^4 - (\pi \times 0.0174/4)^4)}{(2 \times 0.110)^2}$$

$$F = 6760.009 \text{ KN}$$

$$\sigma = \frac{F}{A} = \frac{\pi^2 E}{(l/r)^2}$$

But currently force on each stripper tube is 4 Ton=39.24KN

$$A = (\pi \times 0.0232/4)^2 - (\pi \times 0.0172/4)^2$$

$$A = 1.885 \times 10^{-4} \text{ m}^2$$

$$\sigma = \frac{39.24}{1.885 \times 10^{-4}}$$

$$\sigma = 208.169 \text{ MPa}$$

## 2. ANALYSIS

The analysis of the press tool components will be done with the help of the Ansys software. The parts are primarily meshed in the Ansys software with the tetra mesh type. Finally the force is applied on those parts on the basis of the working conditions. The bellow figures show the analysis and their results.

The pillar is meshed with the tetra mesh. The there are four pillar in the design each pillar will take equal load. For each pillar load is equally distributed and load of 196.133KN act on each pillar. The bellow figure shows the meshing, stress distribution and deformation in the pillar.




Figure 6: Pillar in meshed condition.




Figure 7: Stress distribution in pillar



selected material bill of material is created. The analysis is done for important components. Form validation of results shows that the design is safe in working condition. From the current project work the main advantage is multiple components will be pressed in a single press tool. It reduces the cost of other press tool for other component. It increases the productivity of the manufacturing.

## REFERENCES

- [1] Vishwanath M.C, Dr.Ramni and Sampath Kumar L, "Design of Progressive Draw Tool". Volume 3, (2013), IJSRP
- [2] JyothiBhaskar and G SathyaPrakash, "Die design and analysis of progressive tool for can lid lever". Volume 1, (2013), IJREAT
- [3] Mr.Amit D. Madake, Dr.Vinayak R. Naik, Mr.Swapnil and S.Kulkarni, "Development of a Sheet-Metal Component with a Forming Die Using CAE Software Tools (Hyper form) For Design Validation and Improvement", Vol. 3, May.-June. 2013, IJMER, p-1787-1791
- [4] VrushabhMahaveerGhosarwade, and Chandradharappa, "FINITE ELEMENT ANALYSIS OF PROGRESSIVE DIE", Volume: 02, (2015), IRJET
- [5] Md Inaithul Rehaman, P Satish Reddy, Matta Manoj, N.Guru Murthy, "Design and Analysis of Progressive Die for Chain Link Plate", Volume 2, (2014),IJSEAT
- [6] Nimbalkar D.H. and Nandedkar V.M. "Review of Incremental Forming of Sheet Metal Components" Volume 3,2013,IJERA,P-39-51